



**Addendum #1**

**2021 Fairgrounds Fire Suppression**

1. Item #1.6 Needs to be removed, will be using Horn Strobe instead of Water Motor Gong
2. Additional items that need added to bid are in following chart

Item	Description	Unit	Qty	Bid Price	Total Bid Price
1.12	Water Test System 2hr @ 200psi				
1.13	Supply Horn Strobe				
1.14	Replace all water line hangers with correct approved hangers				
1.15	Add and Install sprinkler and correct piping under south crow's nest				
1.16	Add and Install sprinkler and correct piping under east crow's nest				
1.17	Add and Install sprinkler and correct piping in South stair case				
1.18	Add and Install 2 sprinklers and correct piping in closet below south stair case				



1.19	Add and Install sprinkler and correct piping at each of the 5 garage doors when doors are in open position				
1.20	Add and Install 2 sprinklers and correct piping in kitchen above double sink and counters, cut and patch ceiling				
1.21	Add and Install 2 sprinklers and correct piping next to hood in kitchen 1 on the north side and 1 on the west side, cut and patch ceiling				
1.22	Add and Install 3 sprinklers and correct piping next to partition in room by kitchen, cut and patch ceiling				
1.23	Relocate sprinkler in women's bathroom shower, cut and patch ceiling				
1.24	Add and Install additional sprinkler in women's bathroom with correct piping, cut and patch ceiling				
1.25	Add and Install sprinkler and correct piping in broom closet				



Montezuma County  
109 West Main Street Cortez, Room 260  
Cortez, CO 81321

<b>1.26</b>	<b>Relocate the sprinkler and add an additional sprinkler with correct piping in North stair case</b>				
<b>1.27</b>	<b>Add and Install additional needed sprinklers and correct piping in oil tank room</b>				
<b>1.28</b>	<b>Add and Install sprinkler and correct piping at entry of oil tank room</b>				
<b>1.29</b>	<b>Supply and Install inspector test sign on panel in kitchen</b>				